**BP Tank Cleaning Guide** 

BP Tank Cleaning Guide																					
Previous Cargo  Cargo to be Loaded	Naphtha / Clean Condensates / LDF	Avgas	MTBE/ETBE/TAME/Ethanol/Methanol	Leaded Motor Spirit	Unleaded Motor Spirit	Sulphur Free Motor Spirit	Solvents	Jet / Aviation Kerosenes	Kerosenes (undyed)	Kerosenes (dyed)	Gas Oil (undyed)	Gas Oil (dyed)	Sulphur Free Diesel / ULSD	FAME/Biodiesel	Crude Oils / Dirty Condensates	sjio eqnT	Wax Distillate / Vacuum Gas Oil	Atmosphric Residue	Heavy / Medium Fuel Oil	Low Sulphur Fuel Oil (LSFO / LSWR)	Light Fuel Oil (LFO)
Naphtha/Clean Condensates/LDF *																					
Avgas																					
МТВЕ	М	М						М	М	М	М	М	М								
Ethanol/Methanol	М	М						М	М	М	М	М	М								
Leaded Motor Spirit																					
Unleaded Motor Spirit																					
Sulphur Free Motor Spirit																					
Solvents *	РМ	РМ	РМ	РМ	РМ	PM				PM		PM					М				М
Jet / Aviation Kerosenes	РМ	РМ		РМ	РМ	РМ				РМ		РМ									М
Kerosenes (undyed)	Р	Р		Р	Р	Р															
Kerosenes (dyed)	Р	Р		Р	Р	Р															
Un-dyed Gas Oil	Р	Р		Р	Р	Р	Р								Р						
Dyed Gas Oil	Р	Р		Р	Р	Р	Р								Р						
FAME / Biodiesel	М	М	М	М	М	М	M			M					М	М	М				М
Ultra Low Sulphur Diesel/Gas Oil *	РМ	РМ	РМ	РМ	РМ	РМ	РМ			РМ		М									М
Sulphur Free Diesel	РМ	РМ	РМ	РМ	РМ	РМ	РМ														
Crude Oils / Dirty Condensates																					
Lube Oils ★	РМ	РМ		РМ	РМ	РМ	РМ							М		LUB					
Wax Distillate / Vacuum Gas Oil	Р	Р		Р	Р		Р								Р						
Atmospheric Residue	Р	Р		Р	Р		Р								Р						
Heavy / Medium Fuel Oil	РХ	РХ		РХ	РХ		Р								РХ						
Low Sulphur Fuel Oil (LSFO / LSWR)	РХ	PX		PX	РХ		Р								Р						
Light Fuel Oil (LFO)	РХ	РХ		РХ	РХ		Р								Р			Х	Х	Х	

## THIS GUIDE COVERS WHITE OIL CARGOES IN COATED TANKS. AND BLACK OIL / CRUDE CARGOES IN EITHER COATED OR UNCOATED TANKS. P Tanks to be purged to below 2% Hydrocarbon by volume No washing required - strip and drain well Non IG Vessels should be 'Gas Free' M Tanks to be mopped or educted DRY Refer Notes: 1 & 2 X If ROB is less than 0.1%, and purging (if required) is effective, Wash tanks with COLD sea water until tank is clean cargo may be loaded directly on top without washing Refer Notes 1, 2 & 3 Tanks that have been washed for the carriage of these Wash tanks with **HOT** sea water until tank is clean. products must have a final wash with fresh water. Refer Notes 1, 2 & 3 Tank and lines are then to be blown and drained free of water To ensure minimum grade to grade admixture, tanks to be Product NOT to be loaded unless specific instructions LUB stripped dry, pump column and deck lines to be blown and have been issued by BP Head Office drained. Tanks to be visually inspected to ensure min ROB

## Notes:

- 1. Tanks to be stripped dry such that any liquid ROB is confined to the pump well or better.
- 2. Pump columns, deck lines, drops etc are to be blown clear and drained free of all product and water.
- 3. Deck lines, loading drops and cross over lines must be thoroughly washed and drained.
- 4. MTBE/Methanol/Ethanol (oxygenates) Are water miscible, introduction of water into designated tanks should be avoided.
- 5. These tank cleaning guidelines are guidelines only and not to be regarded as BP instructions to inspectors